

NOTE B FROM NOAA CHART 11555 JULY 2002

DANGER AREA

AREA IS OPEN TO UNRESTRICTED SURFACE NAVIGATION BUT ALL VESSELS ARE CAUTIONED NEITHER TO ANCHOR, DREDGE, TRAWL, LAY CABLES, BOTTOM, NOR CONDUCT ANY OTHER SIMILAR TYPE OF OPERATION BECAUSE OF RESIDUAL DANGER FROM MINES ON THE BOTTOM.

NOTES:

SOUNDINGS ARE EXPRESSED IN FEET AND TENTHS AND REFER TO LOCAL M.L.W..
PROJECT SURVEYED WITH DISTRICT SURVEY VESSEL "BEAUFORT", USING D.G.P.S. HORIZONTAL POSITIONING EQUIPMENT AND 200 KHZ SOUNDING EQUIPMENT.
TIDE GAGE LOCATED AT: LIGHT 16
HORIZONTAL DATUM NAD 1983.
NAVIGATION AIDS LOCATED WITH SURVEY VESSEL, ACCURACY +/- 3 METERS.

CURRENT AS OF 3 OCTOBER 2003, AIDS MOVED AND COORDINATES PROVIDED BY D/B SNELL

		EASTING	NORTHING	LATITUDE	LONGITUDE
BUOY	3	2969223	535734	35 10.71056	75 45.34978
BUOY	4	2969454	537004	35 10.91858	75 45.29508
BUOY	5	2966958	538199	35 11.12891	75 45.78820
BUOY	6	2967545	538441	35 11.16563	75 45.66880
LT. BUOY	6A	2967100	539970	35 11.41996	75 45.74810
BUOY	7	2966250	540180	35 11.45913	75 45.91734
CENTERLINE WAYPOINTS					
WAYPOINT	1	2969915	534301	35 10.47071	75 44.22031
WAYPOINT	2	2969171	536782	35 10.88352	75 45.35334
WAYPOINT	3	2967245	538331	35 11.14912	75 45.72973
WAYPOINT	4	2966528	540949	35 11.58435	75 45.85651
WAYPOINT	5	2967940	541555	35 11.64498	75 45.57037
WAYPOINT	6	2970164	541555	35 11.66463	75 45.12269

THE INFORMATION DEPICTED ON THIS MAP REPRESENTS THE RESULT OF SURVEYS MADE ON THE DATE INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME BECAUSE THESE CONDITIONS ARE SUBJECT TO RAPID CHANGE. DUE TO THE SHOALING EVENTS, A PRUDENT MARINER SHOULD NOT RELY EXCLUSIVELY ON THE INFORMATION PROVIDED HERE

OBSTRUCTION:
POSITION APPROXIMATED FROM NOAA CHART 11555

Symbol	Descriptions	Date	Approved
Revisions			

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
WILMINGTON, NORTH CAROLINA

US Army Corps of Engineers

HATTERAS INLET

SURVEYED BY: CRP
DRAWN BY: AGF
CHECKED BY
REVIEWED BY
APPROVED BY
CHIEF, NAVIGATION BRANCH

Scale: 1:4800
Date: 23 SEPTEMBER 2003
MAP FILE NO. RC 105-03-6
Plate Number:
SURVEYED: 21-22 SEPTEMBER 2003
Sheet of

INLETS/HATTERAS/2003/HI092122.CO/.DAT/.XST/.DGN

.../HATTERAS/2003/HI0921.dgn 10/03/2003 02:08:43 PM